


Essential Reference Paper F

New Control Room update

New Monitoring Room as of 14th March



Current work status

- Strip Out 100% complete
- Construction of walls 90% complete
- Air Conditioning 80% complete
- Fresh Air Installation 90% complete
- Electrical Installation 65% complete
- Window Boarding 50% complete
- Plastering 75% complete

We are preparing to move during summer 2019. The exact date will be dependent on BT/Virgin circuit switching.